

Behringer X18, XR18 Hardware V2 Firmware Update

Version 1.25 (18 November 2025)

Improvements

- Bus compressor key source changed from post-comp to pre-comp

Fixed

- X-Touch not showing channel name on EQ page